

JOBMAN

Size chart in cm



Brand; Jobman workwear
Style; 5125 Softshell jacket Hi-vis

Position	XS	S	M	L	XL	2XL	3XL	4XL
1/2 CHEST	51	54	58	62	66	70	74	78
1/2 BOTTOM	49	52	56	60	64	68	72	76
C.B LENGTH fr NECKHOLE	67	68	70	72	74	76	78	80
SLEEVE LENGTH fr HSP to btm sleeve	80,5	81,5	83	84,5	86	87,5	88,5	89,5

All measurements are indicated with tolerance of 1 cm